



NATIONAAL

**BIM**

CONGRES



# ACC Build in de praktijk

BUNGE

# Kwaliteits controle met ACC Build


Westzaan

September 2024



# Ongeëvenaarde voetafdruk van oliehoudende zaden

Bunge is de wereldwijde **nr 1** op het gebied van crush-volumecapaciteit



100+

Grain Elevators



51

Oilseed Processing Plants



26

Port Terminals



29

Oil Refineries



25

Packaging Sites





# Agenda

Het belang van kwaliteitscontrole



Toepassing



Conclusie en vragen

# Team PMO (Project Management Office)

Equito de Palm

BIM MANAGER

---

## Bezig met:

- BIM implementatie
- Data consistentie
- Nieuwe systemen en technieken
- Applicatie landschap
- Informatie management
- Inkaart bregnegen en digitaliseren van werk processen



# Over het Project

211.000 M2



42 x



75 KM



Utrecht - Breda



29.000 M3



11,5 x



50.000 MT



294 x




4.000 st





# Het belang van Kwaliteitscontrole

Het zorgt ervoor dat de standaarden en specificaties van een project worden gehaald, wat dure herwerk voorkomt, de veiligheid verhoogt en klanttevredenheid waarborgt.



# Funcities van Autodesk Build voor Kwaliteitscontrole



Forms / Quality /

## Quality Observation (QO)

Basic Information

1. Issue to

2. Issuing Entity

3. Observation

4. Potential Root Cause

5. Closeout



This form is only visible to you.

### 4. Potential Root Cause

4.1 Root cause

Environment

Machine


Management


Manpower


Material

Method


Other


 Photos


 Issues

 Note


4.2 Other root cause


 Photos


 Issues

 Note


4.3 Description

 Photos

 Issues

 Note

# Workflow voor Kwaliteitscontrole




 **Build**






# Workflow voor Kwaliteitscontrole



<input type="checkbox"/>	Title	ID	Status	Type
<input type="checkbox"/>	Safety Issue	#1414	Completed	SOI Safety Issue
<input type="checkbox"/>	Positive Observation	#1413	Pending	SPO Positive Observ...
<input type="checkbox"/>	Safety Issue	#1412	Open	SOI Safety Issue
<input type="checkbox"/>	Positive Observation	#1411	Completed	SPO Positive Observ...
<input type="checkbox"/>	Safety Incident	#1410	Open	SI Safety Incident
<input type="checkbox"/>	Safety	#1409	Closed	S Safety
<input type="checkbox"/>	Safety Issue	#1408	Completed	SOI Safety Issue
<input type="checkbox"/>	Safety Issue	#1407	Open	SOI Safety Issue
<input type="checkbox"/>	Safety Issue	#1406	Open	SOI Safety Issue
<input type="checkbox"/>	Safety Issue	#1405	Open	SOI Safety Issue
<input type="checkbox"/>	COT TANKFARM PIPE RA...	#1404	Open	COR Coordination
<input type="checkbox"/>	Safety Issue	#1403	Closed	SOI Safety Issue
<input type="checkbox"/>	Safety Issue	#1401	Open	SOI Safety Issue

# Integratie met Field Teams




Build







# Beste Praktijken voor QC met Autodesk Build



# Conclusie en Vragen







BUNGE



an auxalia company

**Bedankt voor  
de aandacht**

**icn bv**

+31 (0)73 750 6 750

info@icn.nl